

## **UPDATES ON INSPECTION REPORT**

**October 9, 2023**

### **WORK THAT HAS BEEN DONE AFTER THE INSPECTION TOOK PLACE**

- The guest bathroom tap is now working
- The spare bedroom pull knobs for the ceiling fan has been put on
- Peel and Stick tiles have been laid under the guest bathroom and the kitchen have been applied
- The green wall is gone, and some fresh pain in bedrooms and hall.